

MV-AV-Oleodynamic device for bundle cutting

Description



Code: *MV-AV*

We recommend using this optional for strip cutting. Take special care when strip cutting round bars as the round bar could accidentally slip, thus breaking the sawband teeth.

NB1 Box - NB2 Box Sprayer for blade lubrication

Description



Code: *NB1 Box - NB2 Box*

The band saw machine can be equipped of a blade and cutting cooling device. To improve the cutting quality and reduce pollution risk, moreover to avoid the risk of pools of cooling liquid on the floor (possible cause of accidental falls), we suggest to use the NB optional.

Description



Code: *RPM2*

This optional allows you to adjust the pressure of the clamping of the cutter vice and the carriage vice. Adjustment must be made separately for each vice and is done by hand, using the handwheel of the valve. The pressure gauge lets you read the pressure change (in bar).

ST Screw

Description

Screw

chips



Code: *ST Coclea*

conveyor

TC-Containement frame for bar cutting

Description



Code: *TC*